BAYONNE BARREL & DRUM

REPORT#

53

O.S.C.

JOE COSENTINO

DATE:

12/07/94

R.M. M.R.ELLIS

DESCRIPTION OF DELIVERY ORDER: Mobilize necessary personnel and equipment to facilitate removal action. Overpack, sample, haz-cat drummed waste on site, to include storage tanks above & below ground, pits, gutters, courtyard and ash/soil piles. Proceed with T & D of drummed waste, rubber, ash/soils and drums related to shredding operations. Further provide any additional support needed to assist with the site removal per the O.S.C. **LOCATION OF WORK:**

150 RAYMOND BLVD. NEWARK, NJ 07105

WEATHER:

Overcast

TEMPERATURE:

50

WORK PERFORMED TODAY BY OHM:

- * Continued the drum shredding operations today, further separating drums that contain labels Hazardous Waste " and any other legible manufacturers labels. Weston TAT documents all labels found with this information.
- * Remobilize project chemist Ken Klinger to assemble the drum logs and provide copies of the existing analytical data generated for the ash / soil piles at the south property, (Dioxin).

* Crew shreds 635 drums today, one load of scrap is removed.

SUBCONTRACTOR SERVICES PERFORMED:

EXCEPTIONS / UNUSUAL CONDITIONS:

- * Clay Duffel off site for the day (personal).
- * M.Ellis off site at 1350 hrs. today, (personal)
- * Steve Wilson off site at 1500 hrs. today. (personal)

CHANGE IN METHOD OR SCOPE. SPECIFIC DIRECTION RECEIVED FROM OSC:

DOCUMENTS SUBMITTED:

MEETINGS HELD, SUBJECT MATTER, DIRECTION AND OR DECISIONS:

COMMENTS:

* Due to excessive use and normal wear and tear, the drum grapplers (hydraulic), will need rebuilding of certain components, this will mean rotation off the job.